


Assembly




Instructions

LITTBUS Tiltbox TO2110, TO2111




1.

Assembly the connection tube in the middle row at the second hole from the bottom, use **screw no. 1**. Connect **screw no 1** with **sleeve no. 3** four holes over the connection tube, (works as overtip protection), and at the second hole from the bottom in the back row.




2.

Place the box. It shall now rest on the connection tube and the two sleeves at the back.



3.

The box will now tip as according to the picture.



4.

When assembling more than one box after each other, use **pinbolt no. 7** to connect the tubes. For the overtip protection and the supporter at the back, use **bolt no. 2** and **sleeve no. 3**.